TROPICAL ATMOSPHERE-OCEAN (TAO) PROGRAM FINAL CRUISE REPORT

RB-15-07

Area: Equatorial Pacific: 8°N 170°W to 8°S 170°W and 8°S 155°W to 8°N 155°W

<u>Itinerary:</u>

RB-15-07 DEP November 10, 2015, Seattle, WA

ARR December 17, 2015, Honolulu, HI

CRUISE DESCRIPTION

The Tropical Atmosphere Ocean (TAO) array consists of 70 buoys utilizing a taut line mooring configuration used to mount data collection sensors for climate research purposes. Fifteen buoys are serviced by JAMSTEC and the remaining 55 buoys from 95°W longitude to 165°E longitude are serviced by National Data Buoy Center (NDBC). Repair and maintenance of the buoys is performed by NDBC contracted personnel on an annual basis utilizing the NOAA Ships and other contract vessels.

NDBC Points of Contact

NDBC Operations Branch Chief NDBC Operations Manager

Steve Cucullu Jeff Jenner

National Data Buoy Center National Data Buoy Center

Building 3205 Building 3205

Stennis Space Center, MS 39529 Stennis Space Center, MS 39529

228-688-3804 228-688-2784

Email: stephen.cucullu@noaa.gov Email: jeff.jenner@noaa.gov

TAO Cruise Objective and Plan:

The objective of this cruise was the maintenance of the TAO Array along the 170°W and 155°W meridians. Drifting DART Station 46407 was recovered during this cruise. A PMEL Prawler mooring at 2°N 155°W was also recovered.

The scientific complement for the cruise embarked at Seattle, WA on November 9, 2015. The ship departed on November 10, 2015 and conducted operations as listed in Section 2.1. The ship arrived at Honolulu, HI on December 17, 2015.

1.0 **PERSONNEL**

1.1 <u>CRUISE LEAD AND PARTICIPATING SCIENTISTS</u>:

Cruise Lead: Brian Lake

Participating Scientists:

Name	Gender	Nationality	Affiliation
Brian Lake	M	US	NOAA/NDBC
James Coleman	M	US	NOAA/NDBC
Rodney Watkins	M	US	NOAA/NDBC
David Ball	M	US	NOAA/NDBC

2.0 **OPERATIONS**

2.1 TAO Data Recovery Summary

Mooring Operations conducted are shown in the tables below. The following provides details on the data recovery efforts for the buoys serviced. All noted times in this summary report are Coordinated Universal Time (UTC):

Cruise Summary

Buoy Site: DART Drifter 46D07		
Mooring Operation: Recovery	Mooring ID#: 46407	
Deployed Location: 42-39.4N/128-48.6W	Deployed Date: 3/7/14	
Recovered Location: 30-31.68N/150-17.4W	Recovered Date: 11/18/15	
Sensors/Equipment Lost at Sea: None		
Sensors Damaged/Fouled: None		
Fishing/Vandalism: Buoy was adrift		
General Comments: Mooring failed at the fishbite eyesplice below chain.		

Buoy Site: 8N 170W	
Mooring Operation: Recovery	Mooring ID#: DM095
Deployed Location: 08-01.48N/170-03.16W	Deployed Date: 10/11/14
Recovered Location: 08-00.30N/170-03.30W	Recovered Date: 11/2515
Sensors/Equipment Lost at Sea: NA	

Sensors Damaged/Fouled: SSC, T25-T50 fouled. Several sensors out of their mount.				
Fishing/Vandalism:				
General Comments: Routine recovery				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
SST/SSC	11/17/14	SST too high	None	
RH	4/29/15	Saturated	None	
AT	4/4/15	Too low	None	

Buoy Site: 8N 170W	Mooring Depth: 5522 m	
Mooring Operation: Deployment	Mooring ID#: DM149	
Deployed Location: 07-59.51N/170-06.06W	Deployed Date: 11/26/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 5N 170W				
Mooring Operation: Recovery		Mooring ID#: DM096		
Deployed Location: 05	-00.96N/169-59.51W	Deployed Date: 10/12	Deployed Date: 10/12/14	
Recovered Location: 0	5-00.4N/169-59.2W	Recovered Date: 11/2	Recovered Date: 11/26/15	
Sensors/Equipment Lo	ost at Sea: Tube, ATRH,	Anemometer missing.		
Sensors Damaged/Fou	led: SSC fouled			
Fishing/Vandalism: Topside instruments were removed.				
General Comments: None				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			Field Service	
Observations				
T100	12/31/14	Missing	None	
Tube	1/15/15	No transmits	Vandalism,	
			Lost at Sea	

Buoy Site: 5N 170W	Mooring Depth: 5752 m	
Mooring Operation: Deployment	Mooring ID#: DM150	
Deployed Location: 05-01.4N/169-59.4W	Deployed Date: 11/27/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 2N 170W			
Mooring Operation: Recovery	Mooring ID#: DM097		
Deployed Location: 02-02.08N/169-59.04W	Deployed Date: 10/13/14		
Recovered Location: 02-02.3N/169-59.82W	Recovered Date: 11/28/15		
Sensors/Equipment Lost at Sea: NA			
Sensors Damaged/Fouled: SSC, T25 fouled.			
Fishing/Vandalism: T100-T200, TP500 all fouled with longline			
General Comments: None			

Buoy Site: 2N 170W	Mooring Depth: 5388 m	
Mooring Operation: Deployment	Mooring ID#: DM151	
Deployed Location: 02-01.78N/170-00.23W	Deployed Date: 11/28/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 0 170W Flu	ıx/CO2			
Mooring Operation: Recovery		Mooring ID#: DM098		
Deployed Location: 00	0-01.36S/170-01.43W	Deployed Date: 10/15/14		
Recovered Location: 0	00-00.85S/169-59.52W	Recovered Date: 11/2	Recovered Date: 11/29/15	
Sensors/Equipment Lo	ost at Sea: NA			
Sensors Damaged/Fou	led: SWR, LWR fouled.	SSC-T25 fouled.		
Fishing/Vandalism: No	one			
General Comments: R	outine Recovery			
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			Field Service	
			Observations	
V10	12/31/14	Missing	None	
C10	8/31/15	Conductivity too low	Sensor fouled	
WDIR	10/2/15	Erratic	None	
All Inductive	10/19/14	Significant data losses	None	

Buoy Site: 0 170W Flux/CO2	Mooring Depth: 5602 m		
Mooring Operation: Deployment	Mooring ID#: DM152		
Deployed Location: 00-01.14S/170-01.77W	Deployed Date: 11/30/15		
Pre-Deployment On Deck Instrument Failures: None			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged During Deployment: None			

General Comments: CT75 sensor's temperature reading is only correct at minute 10, 30 and 50 in the hourly data.

Buoy Site: 0 170W AD	CP		
Mooring Operation: Recovery Mooring ID#: KA018			3
Deployed Location: 00	Deployed Location: 00-00.19N/169-43.84W Deployed Date: 10/13/14		
Recovered Location: 0	Recovered Location: 00-00.192N/169-43.84W Recovered Date: 11/30/15		
Sensors/Equipment Lo	ost at Sea: None		
Sensors Damaged/Fou	led: None		
Fishing/Vandalism: No	one		
General Comments: N	Ione		
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations

Buoy Site: 0 170W ADCP	Mooring Depth: 5448 m	
Mooring Operation: Deployment	Mooring ID#: KA019	
Deployed Location: 00-00.082S/169-43.68W	Deployed Date: 12/01/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 2S 170W				
Mooring Operation: Recovery		Mooring ID#: DM099		
Deployed Location: 02-10.04S/170-00.801W Deployed		Deployed Date: 10/16	oyed Date: 10/16/14	
Recovered Location: 0	Recovered Location: 02-09.25S/169-59.7W Recovered Date: 12/01/15			
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: SSC fouled				
Fishing/Vandalism: None				
General Comments: Several sensors out of their mount.				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
T25	3/11/15	Missing	Low Battery	

Buoy Site: 2S 170W	Mooring Depth: 4690 m	
Mooring Operation: Deployment	Mooring ID#: DM153	
Deployed Location: 02-09.42S/170-00.09W	Deployed Date: 12/01/15	
Pre-Deployment On Deck Instrument Failures: None		

Sensors/Equipment Lost at Sea: None	
Sensors Damaged During Deployment: None	
General Comments: None.	

Buoy Site: 5S 170W				
Mooring Operation: Recovery Mooring ID#: DM100		0		
Deployed Location: 04	-59.96S/170-00.81W	Deployed Date: 10/17/14		
Recovered Location: 0	overed Location: 04-58.41S/169-59.46W			
Sensors/Equipment Lo	ost at Sea: None			
Sensors Damaged/Fou	led: SSC-T50 fouled.			
Fishing/Vandalism: No	one			
General Comments: N	one			
Site Sensor Failures	Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			
Observations				
SSC	7/16/15	Conductivity too low	Sensor fouled	
T25	9/21/15	Missing	No communication	

Buoy Site: 5S 170W	Mooring Depth: 5419 m	
Mooring Operation: Deployment	Mooring ID#: DM154	
Deployed Location: 04-59.19S/169-59.04W	Deployed Date: 12/03/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 8S 170W				
Mooring Operation: Recovery Mooring ID#: DM101		1		
Deployed Location: 07-59.43S/170-01.30W Deployed Date: 10/17/14		7/14		
Recovered Location: 0	Recovered Location: 07-58.08S/170-01.20W Recovered Date: 12/03/15			
Sensors/Equipment Lo	ost at Sea: None			
Sensors Damaged/Fouled: None				
Fishing/Vandalism: None				
General Comments: Knot in Nilspin at ~225 m.				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
AT	8/27/15	Erratic	None	
All Inductive Data	4/10/15	Intermittent	None	

Buoy Site: 8S 170W	Mooring Depth: 5375 m
---------------------------	------------------------------

Mooring Operation: Deployment	Mooring ID#: DM155	
Deployed Location: 07-57.8S/170-01.6W	Deployed Date: 12/04/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Original Payload tube was replaced early in the cruise due to wireless		
comms. issues.		

Buoy Site: 8S 155W			
Mooring Operation: Recovery Mooring ID#: DM107			7
Deployed Location: 08-17.41S/155-03.41W Deployed Date: 11/14/14			4/14
Recovered Location: 08-16.97S/155-03.18W Recovered Date: 12/09/15			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: SSC-T50 fouled. Several sensors out of mount			
Fishing/Vandalism: None			
General Comments: None			
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			
			Observations
WDIR	5/3/15	Offset $> 40^{\circ}$	None

Buoy Site: 8S 155W	Mooring Depth: 5339 m	
Mooring Operation: Deployment	Mooring ID#: DM156	
Deployed Location: 08-16.74S/155-02.67W	Deployed Date: 12/10/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment		

Buoy Site: 5S 155W				
Mooring Operation: R	Mooring Operation: Recovery Mooring ID#: DM108		8	
Deployed Location: 05	5-00.018S/154-59.07W	Deployed Date: 11/15/14		
Recovered Location: 0	Recovered Location: 04-59.67S/154-58.2W Recovered Date: 12/10/15			
Sensors/Equipment Lo	Sensors/Equipment Lost at Sea: ATRH lost at sea			
Sensors Damaged/Fouled: SSC-T50 fouled				
Fishing/Vandalism: Possible vandalism, ATRH seems to have been removed.				
General Comments: None				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
AT/RH	9/15/15	Excessive values	Vandalism,	

Sensor lost at sea		

Buoy Site: 5S 155W	Mooring Depth: 5038 m	
Mooring Operation: Deployment	Mooring ID#: DM157	
Deployed Location: 04-58.96S/154-57.023W	Deployed Date: 12/10/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 2S 155W				
Mooring Operation: Recovery		Mooring ID#: DM10	Mooring ID#: DM109	
Deployed Location: 01-58.4S/155-00.9W		Deployed Date: 11/1	Deployed Date: 11/17/14	
Recovered Location: 0	1-57.88S/155-00.07W	Recovered Date: 12/	Recovered Date: 12/11/15	
Sensors/Equipment Lo	ost at Sea: None			
Sensors Damaged/Fou	led: SSC fouled.			
Fishing/Vandalism: Hawser tied to tower, longline throughout the mooring.				
General Comments: None			-	
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service	
			Observations	
All Inductive Data	10/23/15	Missing	Vandalism, Long line	
			gear entanglement	
AT/RH	11/30/15	Excessive values	Vandalism	
Tube	12/5/15	No transmits	Vandalism	

Buoy Site: 2S 155W	Mooring Depth: 4989 m	
Mooring Operation: Deployment	Mooring ID#: DM158	
Deployed Location: 01-58.020S/154-59.43W	Deployed Date: 12/11/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: TP300 stopped transmitting upon deployment.		

Buoy Site: 0 155W		
Mooring Operation: Recovery	Mooring ID#: DM110W	
Deployed Location: 00-00.2N/154-55.16W	Deployed Date: 11/17/15	
Recovered Location: 00-00.1N/154-54.66W	Recovered Date: 12/12/15	
Sensors/Equipment Lost at Sea: None		

Sensors Damaged/Fouled: SSC-T50 fouled
Fishing/Vandalism: Longline entangled in mooring from 500 – 550 m.
General Comments: None

Buoy Site: 0 155W	Mooring Depth: 4640 m	
Mooring Operation: Deployment	Mooring ID#: DM159	
Deployed Location: 00-00.01S/154-55.43W	Deployed Date: 12/12/15	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 2N 155W				
Mooring Operation: Recovery		Mooring ID#: DM11	Mooring ID#: DM111	
Deployed Location: 01	-59.08N/154-58.38W	Deployed Date: 11/18/14		
Recovered Location: (01-58.88N/154-58.55W	Recovered Date: 12/	13/15	
Sensors/Equipment Lo	Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: SSC fouled				
Fishing/Vandalism: Longline throughout the entire mooring.				
General Comments: None				
Site Sensor Failures	Date Data Flagged	Why data failed	Field Service	
			Observations	
RH	3/22/15	Too low	Vandalism	
SST	3/29/15	Erratic	Sensor damaged	

Buoy Site: 2N 155W	Mooring Depth: 46571 m	
Mooring Operation: Deployment	Mooring ID#: DM160	
Deployed Location: 01-59.53N/154-58.133W Deployed Date: 12/14/15		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Routine deployment.		

Buoy Site: 5N 155W		
Mooring Operation: Recovery	Mooring ID#: DM112	
Deployed Location: 05-00.1N/154-57.1W	Deployed Date: 11/20/14	
Recovered Location: 04-59.617N/154-56.7W Recovered Date: 12/14/15		
Sensors/Equipment Lost at Sea: None		

Sensors Damaged/Fouled: None			
Fishing/Vandalism: None			
General Comments: None			
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations
SST	3/29/15	Too low	None

Buoy Site: 5N 155W	Mooring Depth: 4588 m	
Mooring Operation: Deployment Mooring ID#: DM161		
Deployed Location: 04-59.84N/154-56.96W Deployed Date: 12/15/15		
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: Wind speed out on deployment, wind direction good		
General Comments: Too rough to lauch the small boat for an emometer replacement.		

2.2 <u>CTD Casts Completed</u>

A Sea-Bird 911plus CTD with dual temperature and conductivity sensors was provided by the OMAO. Temperature and conductivity sensors are calibrated yearly at Sea-Bird and sent in for diagnostics as necessary.

The following outlines the CTD casts completed during the cruise:

CTDs				
Coordinates	Date	Cast #	Comments	
8N 170W	11/25/15	RB15078N170W	3000 m	
7N 170W	11/26/15	RB15077N170W	1000 m	
6N 170W	11/26/15	RB15076N170W	1000 m	
5N 170W	11/27/15	RB15075N170W	1000 m	
4N 170W	11/27/15	RB15074N170W	1000 m	
3N 170W	11/28/15	RB15073N170W	3000 m	
2N 170W	11/28/15	RB15072N170W	1000 m	
1N 170W	11/29/15	RB15071N170W	1000 m	
0N 170W	11/29/15	RB15070N170W	3000 m	
1S 170W	12/1/15	RB15071S170W	1000 m	
2S 170W	12/1/15	RB15072S170W	1000 m	
3S 170W	12/2/15	RB15073S170W	1000 m	
4S 170W	12/2/15	RB15074S170W	1000 m	
5S 170W	12/3/15	RB15075S170W	1000 m	
6S 170W	12/3/15	RB15076S170W	1000 m	
7S 170W	12/3/15	RB15077S170W	1000 m	

8S 170W	12/4/15	RB15078S170W	3000 m
8S 155W	12/9/15	RB15078S155W	3000 m
5S 155W	12/11/15	RB15075S155W	1000 m
2S 155W	12/12/15	RB15072S155W	1000 m
1S 155W	12/12/15	RB15071S155W	1000 m
0 155W	12/12/15	RB15070S155W	3000 m
1N 155W	12/13/15	RB15071N155W	1000 m
2N 155W	12/13/15	RB15072N155W	1000 m
5N 155W	12/15/15	RB15075N155W	1000 m

2.3 <u>Ancillary Science Projects Completed on the Cruise</u>

The following outlines the ancillary science work performed in conjunction with the TAO operations on the cruise:

Pacific Marine Environmental Laboratory (PMEL) Argo Profiling CTD Floats

Fifteen (11) Argo floats were scheduled for deployment on this cruise. All Argo Float deployments were completed as scheduled.

Questions concerning ARGO Floats should be directed to:

Gregory Johnson, NOAA/PMEL or Elizabeth Steffen, NOAA/PMEL

Tel: (206) 526-6806 Tel: (206) 526-6747

E-mail: pmel_floats@noaa.gov E-mail: pmel_floats@noaa.gov

The following outlines the Argo floats deployed during the cruise:

Argo Floats					
Coordinates	Date	SN#	Comments		
37-40.89N/136-43.13W	11/15/15	590			
11-00.50N/167-22.52W	11/24/15	501			
09-30.44N/168-42.57W	11/25/15	487			
07-59.65N/170-05.81W	11/26/15	486			
05-00.72N/169-59.13W	11/27/15	485			
02-01.80N/169-59.95W	11/28/15	484			
00-00.75S/170-00.64W	11/30/15	479			
01-57.43S/154-59.12W	12/12/15	475			
00-00.54N/154-55.26W	12/13/15	474			
01-59.06N/154-57.08W	12/14/15	473			
05-00.11N/154-56.99W	12/15/15	472			

Atlantic Oceanographic and Meteorological Laboratory (AMOL) Surface Drifting Floats

Twenty six (18) AOML Surface Drifters were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All AOML Surface Drifter deployments were completed as scheduled.

Questions concerning AOML Surface Drifters should be directed to:

Shaun Dolk, NOAA/AOML Global Drifter Center,

Tel: (305) 361-4546 Fax: (305) 361-4436

E-mail: shaun.dolk@noaa.gov

The following outlines the AOML Drifting floats deployed during this cruise:

AOML Drifters					
Coordinates	Date	SN#	Comments		
04-59.97N/170-00.52W	11/27/15	139626			
05-59.96N/170-00.52W	11/27/15	139722			
02-59.84N/169-59.38W	11/27/15	139620			
02-59.80N/169-59.38W	11/27/15	139624			
00-00.74S/170-00.66W	11/30/15	139628			
00-00.74S/170-00.66W	11/30/15	139623			
03-00.10S/170-00.37W	12/02/15	139621			
03-00.10S/170-00.37W	12/02/15	139622			
04-59.21S/169-58.54W	12/03/15	139934			
04-59.21S/169-58.54W	12/03/15	139936			
04-58.97S/154-56.95W	12/11/15	139933			
04-58.97S/154-56.95W	12/11/15	139935			
02-59.86S/155-02.66W	12/11/15	139932			
02-59.86S/155-02.66W	12/11/15	139931			
00-00.54N/154-55.26W	12/13/15	139928			
02-59.51N/155-00.73W	12/14/15	139930			
04-59.95N/154-57.04W	12/15/15	139927			
04-59.95N/154-57.04W	12/15/15	139929			